



335 S. Centerville Turnpike Suite D, Chesapeake VA 23322 | Tel (703)259-8550 | Fax (703) 259-8548 | www.TachyonDynamics.com

AUGUST 15, 2025

Keysight

1400 Fountaingrove Parkway

Santa Rosa, CA 95403-1738

References:

1. NIST SP 800-53 Rev 5, <https://csrc.nist.gov/pubs/sp/800/53/r5/upd1/final>
2. NIST SP 800-53A Rev 5, <https://csrc.nist.gov/pubs/sp/800/53/a/r5/final>
3. DISA Control Correlation Identifier (CCI), <https://www.cyber.mil/stigs/cci/>
4. DISA Security Requirements Guidelines (SRG) and Security Technical Implementation Guidelines (STIG) documentation repository, <https://www.cyber.mil/stigs/downloads>

Subject: IAVerify Verified Product – Keysight Vision Packet Broker, Software version 6.0.1

The Vision Packet Broker has been validated against all applicable requirements in Reference (4). Each requirement has been sourced from the DoD CCI in References (1), (2), and (3). Details on all configurations and implementation can be obtained in the final Assessment Report. The Vision Packet Broker running software, version 6.0.1 meets all requirements, is in an excellent cybersecurity state. and is recommended for procurement.

Note: On 14 March 2023, Keysight also underwent a DoD Approved Products List Certification (DoDIN APL) test for the Vision Packet Broker.

Signed

Jeremy Duncan

CEO and President

Tachyon Dynamics

jduncan@tachyondynamics.com